			Section 2	- Primary - Primary Secondary	Section 2	- Alternate - Alternate - Primary			
			Daikin Appl	ied Americas	Bernhard	MCC, LLC			
			Irvin	g, TX	Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section	Section 1: Downtown Fort Worth (East) - HVAC Chiller Inspection & Repair Services								
Admi	Administration Building								
1	McQuay, WSC063- DAAAM, Serial: STNU041000117 - Stop Inspection	1	\$ 3,030.96	\$ 3,030.96	\$ 5,890.00	\$ 5,890.00			
2	McQuay, WSC063- DAAAM, Serial: STNU041000117 - Run Inspection	3	\$ 606.20	\$ 1,818.60	\$ 250.00	\$ 750.00			
3	McQuay, WSC063- DAAAM, Serial: STNU041000127 - Stop Inspection	1	\$ 3,030.97	\$ 3,030.97	\$ 5,890.00	\$ 5,890.00			
4	McQuay, WSC063- DAAAM, Serial: STNU041000127 - Run Inspection	3	\$ 606.20	\$ 1,818.60	\$ 250.00	\$ 750.00			
5	York, YKCCCSQ3-EKGS, Serial: SCYM-245880 - Stop Inspection	1	\$ 3,030.97	\$ 3,030.97	\$ 7,055.00	\$ 7,055.00			
6	York, YKCCCSQ3-EKGS, Serial: SCYM-245880 - Run Inspection	3	\$ 606.20	\$ 1,818.60	\$ 350.00	\$ 1,050.00			
7	York, YKCCCSQ3-EKGS, Serial: YKCCCSQ3-EKGS - Stop Inspection		\$ 3,030.97	\$ 3,030.97	\$ 7,055.00	\$ 7,055.00			

			Section 2	- Primary - Primary Secondary	Section 2	- Alternate - Alternate - Primary			
			Daikin Appli	ied Americas	Bernhard	MCC, LLC			
			Irving, TX		Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section	Section 1: Downtown Fort Worth (East) - HVAC Chiller Inspection & Repair Services								
Admi	nistration Building								
8	York, YKCCCSQ3-EKGS, Serial: YKCCCSQ3-EKGS - Run Inspection	3	\$ 606.20	\$ 1,818.60	\$ 350.00	\$ 1,050.00			
Crimi	nal Courts Building								
9	McQuay, PEH063, Serial: 57K81046 - Stop Inspection	1	\$ 3,030.99	\$ 3,030.99	\$ 6,196.00	\$ 6,196.00			
10	McQuay, PEH063, Serial: 57K81046 - Run Inspection	3	\$ 606.19	\$ 1,818.57	\$ 218.00	\$ 654.00			
11	McQuay, PEH063, Serial: 57K81051 - Stop Inspection	1	\$ 3,031.00	\$ 3,031.00	\$ 6,196.00	\$ 6,196.00			
12	McQuay, PEH063, Serial: 57K81051 - Run Inspection	3	\$ 606.19	\$ 1,818.57	\$ 218.00	\$ 654.00			
Crimi	nal Justice Building								
13	Carrier, 30HXC106RYE540KA, Serial: 1002Q01270 - Stop Inspection	1	\$ 2,880.73	\$ 2,880.73	\$ 5,988.00	\$ 5,988.00			

			Section 2	l - Primary - Primary Secondary	Section 2	- Alternate - Alternate - Primary			
			Daikin Appl	ied Americas	Bernhard	MCC, LLC			
			Irvin	g, TX	Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Secti	Section 1: Downtown Fort Worth (East) - HVAC Chiller Inspection & Repair Services								
Crimi	inal Justice Building								
14	Carrier, 30HXC106RYE540KA, Serial: 1002Q01270 - Run Inspection	3	\$ 606.20	\$ 1,818.60	\$ 204.00	\$ 612.00			
15	Carrier, 30HXC106RYE540KA, Serial: 1797F69785 - Stop Inspection	1	\$ 2,880.70	\$ 2,880.70	\$ 5,988.00	\$ 5,988.00			
16	Carrier, 30HXC106RYE540KA, Serial: 1797F69785 - Run Inspection	3	\$ 606.20	\$ 1,818.60	\$ 204.00	\$ 612.00			
Fami	ly Law Center				-				
17	McQuay, WSC087- BAAAM, Serial: STNU030700092 - Stop Inspection	1	\$ 2,422.58	\$ 2,422.58	\$ 6,158.00	\$ 6,158.00			
18	McQuay, WSC087- BAAAM, Serial: STNU030700092 - Run Inspection	3	\$ 1,009.33	\$ 3,027.99	\$ 225.00	\$ 675.00			
19	McQuay, WSC087- BAAAM, Serial: STNU030700103 - Stop inspection	1	\$ 2,422.58	\$ 2,422.58	\$ 6,158.00	\$ 6,158.00			

			Section 1 - Primary Section 2 - Primary Section 3 - Secondary			Section 1 - Alternate Section 2 - Alternate Section 3 - Primary			
			Daikin Appl	ied /	Americas		Bernhard	MC	C, LLC
			Irvin	Irving, TX			Irvin	g, T)	×
			HUB:		No		HUB:		No
			Co-Op:		Yes		Co-Op:		Yes
Item	Description	Qty	Unit		Ext		Unit		Ext
Section	Section 1: Downtown Fort Worth (East) - HVAC Chiller Inspection & Repair Services								
	ly Law Center		,		•		•		
	McQuay, WSC087-								
20	BAAAM, Serial: STNU030700103 - Run inspection	3	\$ 1,009.33	\$	3,027.99	\$	225.00	\$	675.00
21	McQuay, WSC087- BAAAM, Serial: STNU030700113 - Stop Inspection	1	\$ 2,422.57	\$	2,422.57	\$	6,158.00	\$	6,158.00
22	McQuay, WSC087- BAAAM, Serial: STNU030700113 - Run Inspection	3	\$ 1,009.33	\$	3,027.99	\$	225.00	\$	675.00
Tom	Vandergriff Civil Courts Buil	ding							
23	York, YKDCDCQ5-EKGS, Serial: SCAM-580740 - Stop Inspection	1	\$ 3,606.01	\$	3,606.01	\$	7,491.00	\$	7,491.00
24	York, YKDCDCQ5-EKGS, Serial: SCAM-580740 - Run Inspection	3	\$ 701.16	\$	2,103.48	\$	225.00	\$	675.00
25	York, YKDCDCQ5-EKGS, Serial: SCAM-580420 - Stop Inspection	1	\$ 3,606.01	\$	3,606.01	\$	7,491.00	\$	7,491.00
26	York, YKDCDCQ5-EKGS, Serial: SCAM-580420 - Run Inspection Response from Trane U.S. Inc.	3	\$ 701.16		2,103.48	\$	225.00	\$	675.00

			Section 1 - Primary Section 2 - Primary Section 3 - Secondary		Section 1 - Alternate Section 2 - Alternate Section 3 - Primary			
			Daikin Appl	ied Americas	Bernhard	MCC, LLC		
			Irvin	g, TX	Irvin	g, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Section 1: Downtown Fort Worth (East) - HVAC Chiller Inspection & Repair Services								
Tom '	Vandergriff Civil Courts Buil	ding						
27	York, YKDCDCQ5-EKGS, Serial: SCAM-580580 - Stop Inspection	1	\$ 3,606.01	\$ 3,606.01	\$ 7,491.00	\$ 7,491.00		
28	York, YKDCDCQ5-EKGS, Serial: SCAM-580580 - Run Inspection	3	\$ 701.17	\$ 2,103.51	\$ 225.00	\$ 675.00		
Repa	ir Service							
29	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	200	\$ 135.00	\$ 27,000.00	\$ 97.00	\$ 19,400.00		
30	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	10	\$ 202.50	\$ 2,025.00	\$ 115.00	\$ 1,150.00		
31	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	\$ 270.00	\$ 270.00	\$ 115.00	\$ 115.00		
	Subtotal Section 1		\$	101,271.23	\$ 122,052.00			
	Parts Mark-Up Section 1	2	5%	20%				

			Section 2	l - Primary - Primary Secondary	Section 1 - Alternate Section 2 - Alternate Section 3 - Primary				
			Daikin Applied Americas		Bernhard	MCC, LLC			
			Irvin	g, TX	Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
	Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services 350 West Belknap Building								
1	Carrier, 30GXN204F650MH, Serial: 1903F31002 - Stop Inspection	1	\$ 984.28	\$ 984.28	\$ 3,984.00	\$ 3,984.00			
2	Carrier, 30GXN204F650MH, Serial: 1903F31002 - Run Inspection	3	\$ 421.80	\$ 1,265.40	\$ 205.00	\$ 615.00			
3	York, YCIV0207S, 2DXM011049 - Stop Inspection	1	\$ 984.28	\$ 984.28	\$ 3,984.00	\$ 3,984.00			
4	York, YCIV0207S, 2DXM011049 - Run Inspection	3	\$ 421.80	\$ 1,265.40	\$ 205.00	\$ 615.00			
5	York, YCWL0156, Serial: 2BVM002985 - Stop Inspection	1	\$ 2,249.61	\$ 2,249.61	\$ 6,312.00	\$ 6,312.00			
6	York, YCWL0156, Serial: 12BVM002985 - Run Inspection	3	\$ 562.40	\$ 1,687.20	\$ 262.00	\$ 786.00			
7	York, YCWL0156, Serial: 2BVM002986 - Stop Inspection	1	\$ 2,249.61	\$ 2,249.61	\$ 6,312.00	\$ 6,312.00			

			Section 2	l - Primary - Primary Secondary	Section 2	- Alternate - Alternate - Primary			
			Daikin Appl	ied Americas	Bernhard	MCC, LLC			
			Irvin	g, TX	Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
	Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services 350 West Belknap Building								
8	York, YCWL0156, Serial: 2BVM002986 - Run Inspection	3	\$ 562.40	\$ 1,687.20	\$ 262.00	\$ 786.00			
9	York, YCWL0156, Serial: 2BVM002987 - Stop Inspection	1	\$ 2,249.61	\$ 2,249.61	\$ 6,312.00	\$ 6,312.00			
10	York, YCWL0156, Serial: 2BVM002987 - Run Inspection	3	\$ 562.40	\$ 1,687.20	\$ 262.00	\$ 786.00			
Corre	ections Center								
11	McQuay, AGZ090DHANN- ER10, Serial: STNU130100073 - Stop Inspection	1	\$ 1,885.00	\$ 1,885.00	\$ 1,993.00	\$ 1,993.00			
12	McQuay, AGZ090DHANN- ER10, Serial: STNU130100073 - Run Inspection	3	\$ 580.00	\$ 1,740.00	\$ 172.00	\$ 516.00			
13	York, YMC2-S2884ABS, Serial: SCJM-735640 - Stop Inspection	1	\$ 3,480.29	\$ 3,480.29	\$ 5,959.00	\$ 5,959.00			
14	York, YMC2-S2884ABS, Serial: SCJM-735640 - Run Inspection Response from Trane U.S. Inc.	3	\$ 580.00	\$ 1,740.00	\$ 419.00	\$ 1,257.00			

			Section 2	1 - Primary 2 - Primary - Secondary	Section 1 - Alternate Section 2 - Alternate Section 3 - Primary					
			Daikin Appl	ied Americas	Bernhard	MCC, LLC				
			Irvin	ıg, TX	Irvin	g, TX				
			HUB:	No	HUB:	No				
			Co-Op:	Yes	Co-Op:	Yes				
Item	Description	Qty	Unit	Ext	Unit	Ext				
	Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services Corrections Center									
15	York, YMC2-S2884ABS, Serial: SCJM735400 - Stop Inspection	1	\$ 3,480.30	\$ 3,480.30	\$ 5,959.00	\$ 5,959.00				
16	York, YMC2-S2884ABS, Serial: SCJM735400 - Run Inspection	3	\$ 580.00	\$ 1,740.00	\$ 419.00	\$ 1,257.00				
Lon E	Evans Correction Center									
17	McQuay, AWS280ADHEVNN- ER10, Serial: STNU101200129 - Stop Inspection	1	\$ 992.16	\$ 992.16	\$ 6,143.00	\$ 6,143.00				
18	McQuay, AWS280ADHEVNN- ER10, Serial: STNU101200129 - Run Inspection	3	\$ 567.04	\$ 1,701.12	\$ 219.00	\$ 657.00				
19	McQuay, WMC290DBS- ER10, Serial: STNU110100213 - Stop Inspection	1	\$ 3,402.24	\$ 3,402.24	\$ 6,143.00	\$ 6,143.00				

			Section 1 - Primary Section 2 - Primary Section 3 - Secondary		Section 1 - Alternate Section 2 - Alternate Section 3 - Primary					
			Daikin Appl	ied Americas	Bernhard	MCC, LLC				
			Irvin	Irving, TX		g, TX				
			HUB:	No	HUB:	No				
			Co-Op:	Yes	Co-Op:	Yes				
Item	Description	Qty	Unit	Ext	Unit	Ext				
	Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services									
20	McQuay, WMC290DBS- ER10, Serial: STNU110100213 - Run Inspection	3	\$ 567.04	\$ 1,701.12	\$ 219.00	\$ 657.00				
21	McQuay, WMC290DBS- ER10, Serial: STNU110200176 - Stop Inspection	1	\$ 3,402.24	\$ 3,402.24	\$ 6,143.00	\$ 6,143.00				
22	McQuay, WMC290DBS- ER10, Serial: STNU110200176 - Run Inspection	3	\$ 567.04	\$ 1,701.12	\$ 219.00	\$ 657.00				
Plaza	Building									
23	Trane, CVHE020FA1, Serial: L90J03382 - Stop Inspection	1	\$ 3,784.35	\$ 3,784.35	\$ 6,534.00	\$ 6,534.00				
24	Trane, CVHE020FA1, Serial: L90J03382 - Run Inspection	3	\$ 605.49	\$ 1,816.47	\$ 222.00	\$ 666.00				
25	Trane, CHEV020FB1, Serial: L90J03383 - Stop Inspection	1	\$ 3,784.35	\$ 3,784.35	\$ 6,534.00	\$ 6,534.00				

			Section 2	l - Primary 2 - Primary 5 Secondary	Section 2	- Alternate - Alternate 3 - Primary				
			Daikin Applied Americas		Bernhard	MCC, LLC				
			Irvin	Irving, TX		g, TX				
			HUB:	No	HUB:	No				
			Co-Op:	Yes	Co-Op:	Yes				
Item	Description	Qty	Unit	Ext	Unit	Ext				
	Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services									
Plaza	Building					r				
26	Trane, CHEV020FB1, Serial: L90J03383 - Run Inspection	3	\$ 605.49	\$ 1,816.47	\$ 222.00	\$ 666.00				
27	Trane, CVHE050FAIC, Serial: L90J03355 - Stop Inspection	1	\$ 3,784.34	\$ 3,784.34	\$ 6,534.00	\$ 6,534.00				
28	Trane, CVHE050FAIC, Serial: L90J03355 - Run Inspection	3	\$ 605.49	\$ 1,816.47	\$ 222.00	\$ 666.00				
Tim C	Curry Criminal Justice Cente	r								
29	York, YKFDFTQ7-CMGS, Serial: SEXM927580 - Stop Inspection	1	\$ 3,784.35	\$ 3,784.35	\$ 6,967.00	\$ 6,967.00				
30	York, YKFDFTQ7-CMGS, Serial: SEXM927580 - Sun Inspection	3	\$ 605.49	\$ 1,816.47	\$ 222.00	\$ 666.00				
31	York, YKFDFTQ7-CMGS, Serial: SEXM927730 - Stop Inspection	1	\$ 3,784.35	\$ 3,784.35	\$ 6,967.00	\$ 6,967.00				

			Section 2	l - Primary - Primary Secondary	Section 2	- Alternate - Alternate 3 - Primary		
			Daikin Appl	ied Americas	Bernhard	MCC, LLC		
			Irving, TX		Irvin	g, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services								
Tim Curry Criminal Justice Center								
32	York, YKFDFTQ7-CMGS, Serial: SEXM927730 - Run Inspection	3	\$ 605.49	\$ 1,816.47	\$ 222.00	\$ 666.00		
33	York, YKFDFTQ7-CMGS, Serial: SGXM927880 - Stop Inspection	1	\$ 3,784.34	\$ 3,784.34	\$ 6,967.00	\$ 6,967.00		
34	York, YKFDFTQ7-CMGS, Serial: SGXM927880 - Run Inspection	3	\$ 605.49	\$ 1,816.47	\$ 222.00	\$ 666.00		
Repa	ir Service							
35	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	410	\$ 135.00	\$ 55,350.00	\$ 97.00	\$ 39,770.00		
36	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	1	\$ 202.50	\$ 202.50	\$ 115.00	\$ 115.00		
37	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	\$ 270.00	\$ 270.00	\$ 115.00	\$ 115.00		

			Section 2	l - Primary - Primary Secondary	Section 2	- Alternate - Alternate - Primary
			Daikin Appl	ied Americas	Bernhard	MCC, LLC
			Irvin	Irving, TX		g, TX
			HUB:	No	HUB:	No
			Co-Op:	Yes	Co-Op:	Yes
Item	Description	Qty	Unit	Ext	Unit	Ext
	on 2: Downtown Fort Worth ir Service	(We	st) - HVAC Ch	iller Inspection	& Repair Servi	ces
	Subtotal Section 2		\$	132,702.78	\$	152,332.00
	Parts Mark-Up Section 2		2	5%	20)%
Sectio	on 3: Suburban Tarrant Cou	inty -	HVAC Chiller	Inspection & F	Repair Services	
Dionn	ne Phillips Bagsby Southwes	st Sul	ocourthouse			
1	Daikin, AWV012, Serial: STNU170800003 - Stop Inspection	1	\$ 2,668.90	\$ 2,668.90	\$ 2,374.00	\$ 2,374.00
2	Daikin, AWV012, Serial: STNU170800003 - Run Inspection	3	\$ 485.24	\$ 1,455.72	\$ 192.00	\$ 576.00
3	Daikin, AWV012, Serial: STNU170800011 - Stop Inspection	1	\$ 2,668.91	\$ 2,668.91	\$ 2,374.00	\$ 2,374.00
4	Daikin, AWV012, Serial: STNU170800011 - Run Inspection	3	\$ 485.24	\$ 1,455.72	\$ 192.00	\$ 576.00
Medio	cal Examiner's Office					
5	McQuay, WMC400DBS- ER10, Serial: STNU110300119 - Stop Inspection	1	\$ 2,831.61	\$ 2,831.61	\$ 3,779.00	\$ 3,779.00

			Section 1 - Primary Section 2 - Primary Section 3 - Secondary		Section 1 - Alternate Section 2 - Alternate Section 3 - Primary				
			Daikin Appl	ied Americas	Bernhard	MCC, LLC			
			Irvin	g, TX	Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
	Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services								
Medio	cal Examiner's Office								
6	McQuay, WMC400DBS- ER10, Serial: STNU110300119 - Run Inspection	3	\$ 566.35	\$ 1,699.05	\$ 207.00	\$ 621.00			
7	McQuay, WMC400DBS- ER10, Serial: STNU110300120 - Stop Inspection	1	\$ 2,831.61	\$ 2,831.61	\$ 3,779.00	\$ 3,779.00			
8	McQuay, WMC400DBS- ER10, Serial: STNU110300120 - Run Inspection	3	\$ 566.35	\$ 1,699.05	\$ 207.00	\$ 621.00			
9	York, YLAA0091HE46XCBB, Serial: 2BBM023332 - Stop Inspection	1	\$ 2,831.60	\$ 2,831.60	\$ 3,779.00	\$ 3,779.00			
10	York, YLAA0091HE46XCBB, Serial: 2BBM023332 - Run Inspection	3	\$ 283.16	\$ 849.48	\$ 207.00	\$ 621.00			
North	neast Annex								
11	McQuay, AGS120C, Serial: STNU050900048 - Stop Inspection Response from Trane U.S. Inc.	1 dba	\$ 1,215.83	\$ 1,215.83	\$ 2,476.00	\$ 2,476.00			

			Section 2	l - Primary - Primary Secondary	Section 1 - Alternate Section 2 - Alternate Section 3 - Primary				
			Daikin Appl	ied Americas	Bernhard	MCC, LLC			
			Irving, TX		Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
	Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services								
12	McQuay, AGS120C, Serial: STNU050900048 - Run Inspection	3	\$ 729.42	\$ 2,188.26	\$ 108.00	\$ 324.00			
North	neast Courthouse								
13	York, YLAA0120SE, Serial: 2BBM023507 - Stop Inspection	1	\$ 2,433.77	\$ 2,433.77	\$ 2,759.00	\$ 2,759.00			
14	York, YLAA0120SE, Serial: 2BBM023507 - Run Inspection	3	\$ 243.38	\$ 730.14	\$ 147.00	\$ 441.00			
15	York, YLAA0120SE, Serial: 2BBM023508 - Stop Inspection	1	\$ 2,433.76	\$ 2,433.76	\$ 2,759.00	\$ 2,759.00			
16	York, YLAA0120SE, Serial: 2BBM023508 - Run Inspection	3	\$ 243.38	\$ 730.14	\$ 147.00	\$ 441.00			
North	nwest Subcourthouse								
17	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900025 - Stop Inspection	1	\$ 1,215.82	\$ 1,215.82	\$ 2,371.00	\$ 2,371.00			

			Section 1 - Primary Section 2 - Primary Section 3 - Secondary		Section 1 - Alternate Section 2 - Alternate Section 3 - Primary			
			Daikin Applied Americas		Bernhard	MCC, LLC		
			Irving, TX		Irvin	g, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services								
18	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900025 - Run Inspection	3	\$ 729.42	\$ 2,188.26	\$ 193.00	\$ 579.00		
19	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900038 - Stop Inspection	1	\$ 1,215.83	\$ 1,215.83	\$ 2,371.00	\$ 2,371.00		
20	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900038 - Run Inspection	3	\$ 729.42	\$ 2,188.26	\$ 193.00	\$ 579.00		
Reso	urce Connection							
21	Carrier, 30GTR050- 521KJ, Serial: 0403F13490 - Stop Inspection	1	\$ 1,703.63	\$ 1,703.63	\$ 2,100.00	\$ 2,100.00		
22	Carrier, 30GTR050- 521KJ, Serial: 0403F13490 - Run Inspection	3	\$ 486.76	\$ 1,460.28	\$ 150.00	\$ 450.00		

			Section 1 - Primary Section 2 - Primary Section 3 - Secondary		Section 1 - Alternate Section 2 - Alternate Section 3 - Primary			
			Daikin Applied Americas		Bernhard	MCC, LLC		
			Irving, TX		Irvin	g, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services Subcourthouse at Mansfield								
Subc	McQuay, AGZ055AS27-							
23	ER10, Serial: STNU990400121 - Stop Inspection	1	\$ 1,098.63	\$ 1,098.63	\$ 1,959.00	\$ 1,959.00		
24	McQuay, AGZ055AS27- ER10, Serial: STNU990400121 - Run Inspection	3	\$ 488.28	\$ 1,464.84	\$ 147.00	\$ 441.00		
25	McQuay, AGZ055AS27- ER10, Serial: STNU021100029 - Stop Inspection	1	\$ 1,098.60	\$ 1,098.60	\$ 1,959.00	\$ 1,959.00		
26	McQuay, AGZ055AS27- ER10, Serial: STNU021100029 - Run Inspection	3	\$ 488.28	\$ 1,464.84	\$ 147.00	\$ 441.00		
Subc	ourthouse in Arlington							
27	McQuay, AGZ060BH727- ER11, Serial: STNU070600189 - Stop Inspection	1	\$ 1,285.18	\$ 1,285.18	\$ 1,947.00	\$ 1,947.00		

			Section 2	l - Primary - Primary Secondary	Section 2	- Alternate - Alternate - Primary			
			Daikin Appl	ied Americas	Bernhard	MCC, LLC			
			Irvin	g, TX	Irvin	g, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
	Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services Subcourthouse in Arlington								
28	McQuay, AGZ060BH727- ER11, Serial: STNU070600189 - Run Inspection	3	\$ 306.00	\$ 918.00	\$ 141.00	\$ 423.00			
29	McQuay, AGZ060BH727- ER11, Serial: STNU070600190 - Stop Inspection	1	\$ 1,285.18	\$ 1,285.18	\$ 1,947.00	\$ 1,947.00			
30	McQuay, AGZ060BH727- ER11, Serial: STNU070600190 - Run Inspection	3	\$ 306.00	\$ 918.00	\$ 141.00	\$ 423.00			
31	McQuay, AGZ060BH727- ER11, Serial: STNU070600192 - Stop Inspection	1	\$ 1,285.20	\$ 1,285.20	\$ 1,947.00	\$ 1,947.00			
32	McQuay, AGZ060BH727- ER11, Serial: STNU070600192 - Run Inspection	3	\$ 306.00	\$ 918.00	\$ 141.00	\$ 423.00			

				Section 1 Section 2 Section 3 -	: - F	Primary		Section 1 - Alternate Section 2 - Alternate Section 3 - Primary		
				aikin Appl	ied	Americas		Bernhard	MCC	C, LLC
				Irvin	g, ⁻	гх		Irvin	g, TX	K
				HUB:		No		HUB:		No
			(Co-Op:		Yes		Co-Op:		Yes
Item	Description	Qty		Unit		Ext		Unit		Ext
	Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services Repair Service									
	Trained Repair Person,									
33	Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	390	\$	135.00	\$	52,650.00	\$	97.00	\$	37,830.00
34	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	20	\$	202.50	\$	4,050.00	\$	115.00	\$	2,300.00
35	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	\$	270.00	\$	270.00	\$	115.00	\$	115.00
	Subtotal Section 3		\$			09,402.10	\$			88,905.00
	Parts Mark-Up Section 3			25	5%			20	%	
	laximum Response Time tandard Call - All Section		6 Hours		s	4 Hours				
Μ	aximum Response Time nergency Call - All Section	-		4 H	our	s		4 Hours		

^{*}Notes: Response from Trane U.S. Inc. dba Trane did not meet specifications for failing to bid all items within a section as required. Response from The Stone Group did not meet specifications for failing to have an individual with a State of Texas Contractor Class A License on staff as required. Evco Partners submitted a no bid response.

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award			
			Carrier C	corporation	The Stor	ne Group*		
			Fort W	orth, TX	Grape	vine, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Section	on 1: Downtown Fort Worth	(Eas	t) - HVAC Chi	ller Inspection	& Repair Serv	vices		
Administration Building								
1	McQuay, WSC063- DAAAM, Serial: STNU041000117 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,547.44	\$ 3,547.44		
2	McQuay, WSC063- DAAAM, Serial: STNU041000117 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
3	McQuay, WSC063- DAAAM, Serial: STNU041000127 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,547.44	\$ 3,547.44		
4	McQuay, WSC063- DAAAM, Serial: STNU041000127 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
5	York, YKCCCSQ3-EKGS, Serial: SCYM-245880 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,121.91	\$ 4,121.91		
6	York, YKCCCSQ3-EKGS, Serial: SCYM-245880 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
7	York, YKCCCSQ3-EKGS, Serial: YKCCCSQ3-EKGS - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,121.91	\$ 4,121.91		

	_		Section 2 -	- Secondary - Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award			
			Carrier C	Corporation	The Stor	ne Group*		
			Fort W	orth, TX	Grape	vine, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Section 1: Downtown Fort Worth (East) - HVAC Chiller Inspection & Repair Services								
Admi	nistration Building							
8	York, YKCCCSQ3-EKGS, Serial: YKCCCSQ3-EKGS - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
Crimi	nal Courts Building							
9	McQuay, PEH063, Serial: 57K81046 - Stop Inspection	1	\$ 5,101.00	\$ 5,101.00	\$ 3,547.44	\$ 3,547.44		
10	McQuay, PEH063, Serial: 57K81046 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
11	McQuay, PEH063, Serial: 57K81051 - Stop Inspection	1	\$ 5,101.00	\$ 5,101.00	\$ 3,547.44	\$ 3,547.44		
12	McQuay, PEH063, Serial: 57K81051 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
Crimi	inal Justice Building							
13	Carrier, 30HXC106RYE540KA, Serial: 1002Q01270 - Stop Inspection	1	\$ 3,200.00	\$ 3,200.00	\$ 4,249.44	\$ 4,249.44		

			Section 2 - Secondary Sect			tion 1 - No Award ion 2 - No Award ion 3 - No Award		
			Carrier C	orporation	The Stor	ne Group*		
			Fort W	orth, TX	Grape	vine, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Secti	on 1: Downtown Fort Worth	(Eas	t) - HVAC Chi	ller Inspection	& Repair Serv	ices		
Criminal Justice Building								
14	Carrier, 30HXC106RYE540KA, Serial: 1002Q01270 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
15	Carrier, 30HXC106RYE540KA, Serial: 1797F69785 - Stop Inspection	1	\$ 3,200.00	\$ 3,200.00	\$ 4,249.44	\$ 4,249.44		
16	Carrier, 30HXC106RYE540KA, Serial: 1797F69785 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
Fami	ly Law Center	-						
17	McQuay, WSC087- BAAAM, Serial: STNU030700092 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,073.94	\$ 4,073.94		
18	McQuay, WSC087- BAAAM, Serial: STNU030700092 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
19	McQuay, WSC087- BAAAM, Serial: STNU030700103 - Stop inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,073.94	\$ 4,073.94		

			Section 1 - Secondary Section 2 - Secondary Section 3 - Alternate		Section 1 - No Award Section 2 - No Award Section 3 - No Award	
			Carrier C	orporation	The Stor	ne Group*
			Fort Worth, TX		Grape	vine, TX
			HUB:	No	HUB:	No
			Co-Op:	Yes	Co-Op:	Yes
Item	Description	Qty	Unit	Ext	Unit	Ext
Section	on 1: Downtown Fort Worth	(Eas	t) - HVAC Chi	ller Inspection	& Repair Serv	vices
	y Law Center		,		•	
	McQuay, WSC087-					
20	BAAAM, Serial: STNU030700103 - Run inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37
21	McQuay, WSC087- BAAAM, Serial: STNU030700113 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,073.94	\$ 4,073.94
22	McQuay, WSC087- BAAAM, Serial: STNU030700113 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37
Tom '	Vandergriff Civil Courts Buil	ding			• •	
23	York, YKDCDCQ5-EKGS, Serial: SCAM-580740 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,297.41	\$ 4,297.41
24	York, YKDCDCQ5-EKGS, Serial: SCAM-580740 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37
25	York, YKDCDCQ5-EKGS, Serial: SCAM-580420 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,297.41	\$ 4,297.41
26	York, YKDCDCQ5-EKGS, Serial: SCAM-580420 - Run Inspection esponse from Trane U.S. Inc. o	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37

			Section 2 -	- Secondary - Secondary - Alternate	Section 2	- No Award - No Award - No Award		
		Carrier C	Corporation	The Stor	ne Group*			
			Fort W	′orth, TX	Grape	vine, TX		
			HUB:	No	HUB:	No		
			Co-Op:	Yes	Co-Op:	Yes		
Item	Description	Qty	Unit	Ext	Unit	Ext		
Section 1: Downtown Fort Worth (East) - HVAC Chiller Inspection & Repair Services								
Tom Vandergriff Civil Courts Building								
27	York, YKDCDCQ5-EKGS, Serial: SCAM-580580 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 4,297.41	\$ 4,297.41		
28	York, YKDCDCQ5-EKGS, Serial: SCAM-580580 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37		
Repa	ir Service							
29	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	200	\$ 130.00	\$ 26,000.00	\$ 138.06	\$ 27,612.00		
30	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	10	\$ 195.00	\$ 1,950.00	\$ 161.46	\$ 1,614.60		
31	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	\$ 260.00	\$ 260.00	\$ 205.92	\$ 205.92		
	Subtotal Section 1		\$	107,702.00	\$	104,496.21		
	Parts Mark-Up Section 1		20	0%	16%			

					Section 1 - No Award Section 2 - No Award Section 3 - No Award				
			Carrier C	corporation	The Stor	ne Group*			
			Fort Worth, TX		Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services 350 West Belknap Building									
1	Carrier, 30GXN204F650MH, Serial: 1903F31002 - Stop Inspection	1	\$ 2,660.00	\$ 2,660.00	\$ 2,372.76	\$ 2,372.76			
2	Carrier, 30GXN204F650MH, Serial: 1903F31002 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 590.85	\$ 1,772.55			
3	York, YCIV0207S, 2DXM011049 - Stop Inspection	1	\$ 2,660.00	\$ 2,660.00	\$ 2,372.76	\$ 2,372.76			
4	York, YCIV0207S, 2DXM011049 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 590.85	\$ 1,772.55			
5	York, YCWL0156, Serial: 2BVM002985 - Stop Inspection	1	\$ 2,941.00	\$ 2,941.00	\$ 2,372.76	\$ 2,372.76			
6	York, YCWL0156, Serial: 12BVM002985 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
7	York, YCWL0156, Serial: 2BVM002986 - Stop Inspection	1	\$ 2,941.00	\$ 2,941.00	\$ 2,372.76	\$ 2,372.76			

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award				
			Carrier C	corporation	The Stone Group*				
			Fort W	orth, TX	Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services 350 West Belknap Building									
8	York, YCWL0156, Serial: 2BVM002986 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
9	York, YCWL0156, Serial: 2BVM002987 - Stop Inspection	1	\$ 2,941.00	\$ 2,941.00	\$ 2,372.76	\$ 2,372.76			
10	York, YCWL0156, Serial: 2BVM002987 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
Corre	ections Center								
11	McQuay, AGZ090DHANN- ER10, Serial: STNU130100073 - Stop Inspection	1	\$ 2,941.00	\$ 2,941.00	\$ 1,203.93	\$ 1,203.93			
12	McQuay, AGZ090DHANN- ER10, Serial: STNU130100073 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
13	York, YMC2-S2884ABS, Serial: SCJM-735640 - Stop Inspection	1	\$ 5,101.00	\$ 5,101.00	\$ 3,316.95	\$ 3,316.95			
	York, YMC2-S2884ABS,								

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award				
			Carrier C	orporation	The Stor	ne Group*			
			Fort W	orth, TX	Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services									
15	York, YMC2-S2884ABS, Serial: SCJM735400 - Stop Inspection	1	\$ 5,101.00	\$ 5,101.00	\$ 3,316.95	\$ 3,316.95			
16	York, YMC2-S2884ABS, Serial: SCJM735400 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
Lon E	Evans Correction Center								
17	McQuay, AWS280ADHEVNN- ER10, Serial: STNU101200129 - Stop Inspection	1	\$ 2,941.00	\$ 2,941.00	\$ 2,314.26	\$ 2,314.26			
18	McQuay, AWS280ADHEVNN- ER10, Serial: STNU101200129 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
19	McQuay, WMC290DBS- ER10, Serial: STNU110100213 - Stop Inspection	1	\$ 4,561.00	\$ 4,561.00	\$ 3,047.85	\$ 3,047.85			

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award					
			Carrier C	orporation	The Stor	ne Group*				
			Fort W	orth, TX	Grape	vine, TX				
			HUB:	No	HUB:	No				
			Co-Op:	Yes	Co-Op:	Yes				
Item	Description	Qty	Unit	Ext	Unit	Ext				
	Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services									
20	McQuay, WMC290DBS- ER10, Serial: STNU110100213 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				
21	McQuay, WMC290DBS- ER10, Serial: STNU110200176 - Stop Inspection	1	\$ 4,561.00	\$ 4,561.00	\$ 3,047.85	\$ 3,047.85				
22	McQuay, WMC290DBS- ER10, Serial: STNU110200176 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				
Plaza	Building									
23	Trane, CVHE020FA1, Serial: L90J03382 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,398.85	\$ 3,398.85				
24	Trane, CVHE020FA1, Serial: L90J03382 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 590.85	\$ 1,772.55				
25	Trane, CHEV020FB1, Serial: L90J03383 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,398.85	\$ 3,398.85				

			Section 2 -	- Secondary Secondary - Alternate	Section 2	1 - No Award 2 - No Award 3 - No Award			
			Carrier C	orporation	The Stor	ne Group*			
			Fort W	orth, TX	Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services									
Plaza	a Building								
26	Trane, CHEV020FB1, Serial: L90J03383 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 590.85	\$ 1,772.55			
27	Trane, CVHE050FAIC, Serial: L90J03355 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,398.85	\$ 3,398.85			
28	Trane, CVHE050FAIC, Serial: L90J03355 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 590.85	\$ 1,772.55			
Tim C	Curry Criminal Justice Cente	r							
29	York, YKFDFTQ7-CMGS, Serial: SEXM927580 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,628.17	\$ 3,628.17			
30	York, YKFDFTQ7-CMGS, Serial: SEXM927580 - Sun Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
31	York, YKFDFTQ7-CMGS, Serial: SEXM927730 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,628.17	\$ 3,628.17			

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award				
			Carrier C	Corporation	The Sto	ne Group*			
			Fort W	orth, TX	Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services Tim Curry Criminal Justice Center									
32	York, YKFDFTQ7-CMGS, Serial: SEXM927730 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
33	York, YKFDFTQ7-CMGS, Serial: SGXM927880 - Stop Inspection	1	\$ 4,021.00	\$ 4,021.00	\$ 3,628.17	\$ 3,628.17			
34	York, YKFDFTQ7-CMGS, Serial: SGXM927880 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
Repa	ir Service								
35	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	410	\$ 130.00	\$ 53,300.00	\$ 138.06	\$ 56,604.60			
36	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	1	\$ 195.00	\$ 195.00	\$ 161.46	\$ 161.46			
37	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	\$ 260.00	\$ 260.00	\$ 205.92	\$ 205.92			

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award					
			Carrier C	Corporation	The Stor	ne Group*				
			Fort W	orth, TX	Grape	vine, TX				
			HUB:	No	HUB:	No				
			Co-Op:	Yes	Co-Op:	Yes				
Item	Description	Qty	Unit	Ext	Unit	Ext				
	Section 2: Downtown Fort Worth (West) - HVAC Chiller Inspection & Repair Services									
Repa	ir Service		^	444 770 00	•	404 007 00				
	Subtotal Section 2 Parts Mark-Up Section 2		\$	<u>144,770.00</u> 0%	\$	<u>131,327.82</u> 6%				
	on 3: Suburban Tarrant Cou	ntv -								
	he Phillips Bagsby Southwes	-								
1	Daikin, AWV012, Serial: STNU170800003 - Stop Inspection	1	\$ 2,120.00	\$ 2,120.00	\$ 2,314.26	\$ 2,314.26				
2	Daikin, AWV012, Serial: STNU170800003 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 590.85	\$ 1,772.55				
3	Daikin, AWV012, Serial: STNU170800011 - Stop Inspection	1	\$ 2,120.00	\$ 2,120.00	\$ 2,314.26	\$ 2,314.26				
4	Daikin, AWV012, Serial: STNU170800011 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 590.85	\$ 1,772.55				
Medio	cal Examiner's Office									
5	McQuay, WMC400DBS- ER10, Serial: STNU110300119 - Stop Inspection	1	\$ 4,561.00	\$ 4,561.00	\$ 2,559.96	\$ 2,559.96				

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award				
			Carrier C	Carrier Corporation		ne Group*			
			Fort W	orth, TX	Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services Medical Examiner's Office									
6	McQuay, WMC400DBS- ER10, Serial: STNU110300119 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
7	McQuay, WMC400DBS- ER10, Serial: STNU110300120 - Stop Inspection	1	\$ 4,561.00	\$ 4,561.00	\$ 2,559.96	\$ 2,559.96			
8	McQuay, WMC400DBS- ER10, Serial: STNU110300120 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
9	York, YLAA0091HE46XCBB, Serial: 2BBM023332 - Stop Inspection	1	\$ 2,660.00	\$ 2,660.00	\$ 1,133.73	\$ 1,133.73			
10	York, YLAA0091HE46XCBB, Serial: 2BBM023332 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
North	east Annex								
11	McQuay, AGS120C, Serial: STNU050900048 - Stop Inspection esponse from Trane U.S. Inc. c	1	\$ 2,660.00	\$ 2,660.00	\$ 1,203.93	\$ 1,203.93			

			Section 2	- Secondary - Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award					
			Carrier C	Corporation	The Stone Group*					
			Fort W	/orth, TX	Grape	vine, TX				
			HUB:	No	HUB:	No				
			Co-Op:	Yes	Co-Op:	Yes				
Item	Description	Qty	Unit	Ext	Unit	Ext				
	Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services									
12	McQuay, AGS120C, Serial: STNU050900048 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				
North	neast Courthouse	-								
13	York, YLAA0120SE, Serial: 2BBM023507 - Stop Inspection	1	\$ 2,120.00	\$ 2,120.00	\$ 1,203.93	\$ 1,203.93				
14	York, YLAA0120SE, Serial: 2BBM023507 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				
15	York, YLAA0120SE, Serial: 2BBM023508 - Stop Inspection	1	\$ 2,120.00	\$ 2,120.00	\$ 1,203.93	\$ 1,203.93				
16	York, YLAA0120SE, Serial: 2BBM023508 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				
North	nwest Subcourthouse									
17	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900025 - Stop Inspection	1	\$ 2,120.00	\$ 2,120.00	\$ 1,203.93	\$ 1,203.93				

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award				
			Carrier C	corporation	The Stor	ne Group*			
			Fort W	orth, TX	Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services									
NOTU	1								
18	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900025 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
19	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900038 - Stop Inspection	1	\$ 2,120.00	\$ 2,120.00	\$ 1,203.93	\$ 1,203.93			
20	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900038 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
Reso	urce Connection								
21	Carrier, 30GTR050- 521KJ, Serial: 0403F13490 - Stop Inspection	1	\$ 1,580.00	\$ 1,580.00	\$ 604.89	\$ 604.89			
22	Carrier, 30GTR050- 521KJ, Serial: 0403F13490 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			

			Section 2 -	- Secondary Secondary - Alternate	Section 2	ection 1 - No Award ection 2 - No Award ection 3 - No Award			
			Carrier C	orporation	The Stor	ne Group*			
			Fort W	orth, TX	Grape	vine, TX			
			HUB:	No	HUB:	No			
			Co-Op:	Yes	Co-Op:	Yes			
Item	Description	Qty	Unit	Ext	Unit	Ext			
Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services Subcourthouse at Mansfield									
23	McQuay, AGZ055AS27- ER10, Serial: STNU990400121 - Stop Inspection	1	\$ 1,580.00	\$ 1,580.00	\$ 604.89	\$ 604.89			
24	McQuay, AGZ055AS27- ER10, Serial: STNU990400121 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
25	McQuay, AGZ055AS27- ER10, Serial: STNU021100029 - Stop Inspection	1	\$ 1,580.00	\$ 1,580.00	\$ 604.89	\$ 604.89			
26	McQuay, AGZ055AS27- ER10, Serial: STNU021100029 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37			
Subc	ourthouse in Arlington								
27	McQuay, AGZ060BH727- ER11, Serial: STNU070600189 - Stop Inspection	1	\$ 1,580.00	\$ 1,580.00	\$ 604.89	\$ 604.89			

			Section 2 -	- Secondary Secondary - Alternate	Section 1 - No Award Section 2 - No Award Section 3 - No Award					
			Carrier C	corporation	The Stor	ne Group*				
			Fort W	orth, TX	Grape	vine, TX				
			HUB:	No	HUB:	No				
			Co-Op:	Yes	Co-Op:	Yes				
Item	Description	Qty	Unit	Ext	Unit	Ext				
	Section 3: Suburban Tarrant County - HVAC Chiller Inspection & Repair Services Subcourthouse in Arlington									
28	McQuay, AGZ060BH727- ER11, Serial: STNU070600189 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				
29	McQuay, AGZ060BH727- ER11, Serial: STNU070600190 - Stop Inspection	1	\$ 1,580.00	\$ 1,580.00	\$ 604.89	\$ 604.89				
30	McQuay, AGZ060BH727- ER11, Serial: STNU070600190 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				
31	McQuay, AGZ060BH727- ER11, Serial: STNU070600192 - Stop Inspection	1	\$ 1,580.00	\$ 1,580.00	\$ 604.89	\$ 604.89				
32	McQuay, AGZ060BH727- ER11, Serial: STNU070600192 - Run Inspection	3	\$ 540.00	\$ 1,620.00	\$ 452.79	\$ 1,358.37				

			Section 1 - Secondary Section 2 - Secondary Section 3 - Alternate				Section 1 - No Award Section 2 - No Award Section 3 - No Award			
			Carrier Corporation				The Stor	ne G	Group*	
				Fort W	orth	n, TX		Grape	vine	, ТХ
				HUB:		No		HUB:		No
			(Co-Op:		Yes	(Co-Op:		Yes
Item	Description	Qty		Unit		Ext		Unit		Ext
	on 3: Suburban Tarrant Cou ir Service	inty -	HV	AC Chiller	Ins	pection & F	Repa	ir Service	s	
33	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	390	\$	130.00	\$:	50,700.00	\$	138.06	\$ 5	53,843.40
34	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	20	\$	195.00	\$	3,900.00	\$	161.46	\$	3,229.20
35	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	\$	260.00	\$	260.00	\$	205.92	\$	205.92
	Subtotal Section 3	I	\$		1	17,422.00	\$		10	0,371.96
	Parts Mark-Up Section 3			20)%			16	6%	
	aximum Response Time tandard Call - All Sections		4 Hours			4 Hours				
	aximum Response Time nergency Call - All Sectior			2 H	our	S	2 Hours			

^{*}Notes: Response from Trane U.S. Inc. dba Trane did not meet specifications for failing to bid all items within a section as required. Response from The Stone Group did not meet specifications for failing to have an individual with a State of Texas Contractor Class A License on staff as required. Evco Partners submitted a no bid response.

			Section 2 -	- No Award No Award No Award	
			Trane U.S. In	ic. dba Trane*	
			Fort We	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
Section	on 1: Downtown Fort Worth	(Eas	t) - HVAC Chille	er Inspection & F	Repair Services
Admi	nistration Building				
1	McQuay, WSC063- DAAAM, Serial: STNU041000117 - Stop Inspection	1	NB	NB	
2	McQuay, WSC063- DAAAM, Serial: STNU041000117 - Run Inspection	3	NB	NB	
3	McQuay, WSC063- DAAAM, Serial: STNU041000127 - Stop Inspection	1	NB	NB	
4	McQuay, WSC063- DAAAM, Serial: STNU041000127 - Run Inspection	3	NB	NB	
5	York, YKCCCSQ3-EKGS, Serial: SCYM-245880 - Stop Inspection	1	NB	NB	
6	York, YKCCCSQ3-EKGS, Serial: SCYM-245880 - Run Inspection	3	NB	NB	
7	York, YKCCCSQ3-EKGS, Serial: YKCCCSQ3-EKGS - Stop Inspection	1	NB	NB	

			Section 1 - Section 2 - Section 3 -		
			Trane U.S. In	ic. dba Trane*	
			Fort We	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
Secti	on 1: Downtown Fort Worth	(Eas	t) - HVAC Chille	er Inspection & F	Repair Services
Admi	nistration Building				
8	York, YKCCCSQ3-EKGS, Serial: YKCCCSQ3-EKGS - Run Inspection	3	NB	NB	
Crimi	inal Courts Building				
9	McQuay, PEH063, Serial: 57K81046 - Stop Inspection	1	NB	NB	
10	McQuay, PEH063, Serial: 57K81046 - Run Inspection	3	NB	NB	
11	McQuay, PEH063, Serial: 57K81051 - Stop Inspection	1	NB	NB	
12	McQuay, PEH063, Serial: 57K81051 - Run Inspection	3	NB	NB	
Crimi	inal Justice Building				
13	Carrier, 30HXC106RYE540KA, Serial: 1002Q01270 - Stop Inspection	1	NB	NB	

			Section 1 - Section 2 - Section 3 -		
			Trane U.S. In	ic. dba Trane*	
			Fort We	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
Secti	on 1: Downtown Fort Worth	(Eas	t) - HVAC Chille	r Inspection & F	Repair Services
Crimi	inal Justice Building				
14	Carrier, 30HXC106RYE540KA, Serial: 1002Q01270 - Run Inspection	3	NB	NB	
15	Carrier, 30HXC106RYE540KA, Serial: 1797F69785 - Stop Inspection	1	NB	NB	
16	Carrier, 30HXC106RYE540KA, Serial: 1797F69785 - Run Inspection	3	NB	NB	
Fami	ly Law Center				
17	McQuay, WSC087- BAAAM, Serial: STNU030700092 - Stop Inspection	1	NB	NB	
18	McQuay, WSC087- BAAAM, Serial: STNU030700092 - Run Inspection	3	NB	NB	
19	McQuay, WSC087- BAAAM, Serial: STNU030700103 - Stop inspection	1	NB	NB	
htes: R	esponse from Trane U.S. Inc. o	ha T	rane did not meet	specifications for	r failing to bid all items within a

			Section 1 - Section 2 - Section 3 -		
			Trane U.S. In	ic. dba Trane*	
			Fort We	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
Secti	on 1: Downtown Fort Worth	(Eas	it) - HVAC Chille	r Inspection & F	Repair Services
	ly Law Center	(
	McQuay, WSC087-				
20	BAAAM, Serial: STNU030700103 - Run inspection	3	NB	NB	
21	McQuay, WSC087- BAAAM, Serial: STNU030700113 - Stop Inspection	1	NB	NB	
22	McQuay, WSC087- BAAAM, Serial: STNU030700113 - Run Inspection	3	NB	NB	
Tom	Vandergriff Civil Courts Buil	ding			
23	York, YKDCDCQ5-EKGS, Serial: SCAM-580740 - Stop Inspection	1	NB	NB	
24	York, YKDCDCQ5-EKGS, Serial: SCAM-580740 - Run Inspection	3	NB	NB	
25	York, YKDCDCQ5-EKGS, Serial: SCAM-580420 - Stop Inspection	1	NB	NB	
26	York, YKDCDCQ5-EKGS, Serial: SCAM-580420 - Run Inspection	3	NB	NB	
tee D	esponse from Trane ILS Inc. (rang did not moot	specifications for	failing to hid all itoms within a

			Section 2 -	- No Award - No Award - No Award	
			Trane U.S. Ir	ic. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
Section	on 1: Downtown Fort Worth	(Eas	t) - HVAC Chille	er Inspection & F	Repair Services
Tom '	Vandergriff Civil Courts Buil	ding			
27	York, YKDCDCQ5-EKGS, Serial: SCAM-580580 - Stop Inspection	1	NB	NB	
28	York, YKDCDCQ5-EKGS, Serial: SCAM-580580 - Run Inspection	3	NB	NB	
Repa	ir Service				
29	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	200	NB	NB	
30	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	10	NB	NB	
31	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	NB	NB	
	Subtotal Section 1	-	N	В	
	Parts Mark-Up Section 1		N	B	

			Section 2 -	- No Award - No Award - No Award	
			Trane U.S. In	ic. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
50 \	West Belknap Building Carrier,				
1	30GXN204F650MH, Serial: 1903F31002 - Stop Inspection	1	NB	NB	
2	Carrier, 30GXN204F650MH, Serial: 1903F31002 - Run Inspection	3	NB	NB	
3	York, YCIV0207S, 2DXM011049 - Stop Inspection	1	NB	NB	
4	York, YCIV0207S, 2DXM011049 - Run Inspection	3	NB	NB	
5	York, YCWL0156, Serial: 2BVM002985 - Stop Inspection	1	NB	NB	
6	York, YCWL0156, Serial: 12BVM002985 - Run Inspection	3	NB	NB	
7	York, YCWL0156, Serial: 2BVM002986 - Stop	1	NB	NB	

		Section 2 -	- No Award No Award No Award		
			Trane U.S. In	ic. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	on 2: Downtown Fort Worth Vest Belknap Building	(We	st) - HVAC Chill	er Inspection &	Repair Services
8	York, YCWL0156, Serial: 2BVM002986 - Run Inspection	3	NB	NB	
9	York, YCWL0156, Serial: 2BVM002987 - Stop Inspection	1	NB	NB	
10	York, YCWL0156, Serial: 2BVM002987 - Run Inspection	3	NB	NB	
Corre	ections Center				
11	McQuay, AGZ090DHANN- ER10, Serial: STNU130100073 - Stop Inspection	1	NB	NB	
12	McQuay, AGZ090DHANN- ER10, Serial: STNU130100073 - Run Inspection	3	NB	NB	
13	York, YMC2-S2884ABS, Serial: SCJM-735640 - Stop Inspection	1	NB	NB	
14	York, YMC2-S2884ABS, Serial: SCJM-735640 - Run Inspection	3	NB	NB	
otos R	esponse from Trane U.S. Inc. o	tha T	rang did not moot	enecifications for	r failing to hid all items within a

			Section 2	- No Award - No Award - No Award	
			Trane U.S. Ir	nc. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	York, YMC2-S2884ABS,	1	NB	NB	
Corre	ections Center				
15	Serial: SCJM735400 - Stop Inspection	1	NB	NB	
16	York, YMC2-S2884ABS, Serial: SCJM735400 - Run Inspection	3	NB	NB	
Lon E	Evans Correction Center				
17	McQuay, AWS280ADHEVNN- ER10, Serial: STNU101200129 - Stop Inspection	1	NB	NB	
18	McQuay, AWS280ADHEVNN- ER10, Serial: STNU101200129 - Run Inspection	3	NB	NB	
19	McQuay, WMC290DBS- ER10, Serial: STNU110100213 - Stop Inspection	1	NB	NB	

				Section 1 - Section 2 - Section 3 -	No	Award	
			Tr	ane U.S. Ir	ıc. d	ba Trane*	
				Fort W	orth,	ТХ	
				HUB:		No	
				Co-Op:		Yes	
Item	Description	Qty		Unit		Ext	
	on 2: Downtown Fort Worth Evans Correction Center	(We	st) -	HVAC Chill	er In	spection &	Repair Services
20	McQuay, WMC290DBS- ER10, Serial: STNU110100213 - Run Inspection	3		NB		NB	
21	McQuay, WMC290DBS- ER10, Serial: STNU110200176 - Stop Inspection	1		NB		NB	
22	McQuay, WMC290DBS- ER10, Serial: STNU110200176 - Run Inspection	3		NB		NB	
Plaza	a Building						
23	Trane, CVHE020FA1, Serial: L90J03382 - Stop Inspection	1	\$	1,385.00	\$	1,385.00	
24	Trane, CVHE020FA1, Serial: L90J03382 - Run Inspection	3	\$	1,385.00	\$	4,155.00	
25	Trane, CHEV020FB1, Serial: L90J03383 - Stop Inspection	1	\$	1,385.00	\$	1,385.00	

			Section 2 -	- No Award - No Award - No Award	
			Trane U.S. Ir	nc. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	ion 2: Downtown Fort Worth	(We	st) - HVAC Chill	er Inspection &	Repair Services
26	Trane, CHEV020FB1, Serial: L90J03383 - Run Inspection	3	\$ 1,385.00	\$ 4,155.00	
27	Trane, CVHE050FAIC, Serial: L90J03355 - Stop Inspection	1	\$ 1,385.00	\$ 1,385.00	
28	Trane, CVHE050FAIC, Serial: L90J03355 - Run Inspection	3	\$ 1,385.00	\$ 4,155.00	
Tim (Curry Criminal Justice Cente	r			
29	York, YKFDFTQ7-CMGS, Serial: SEXM927580 - Stop Inspection	1	NB	NB	
30	York, YKFDFTQ7-CMGS, Serial: SEXM927580 - Sun Inspection	3	NB	NB	
31	York, YKFDFTQ7-CMGS, Serial: SEXM927730 - Stop Inspection	1	NB	NB	

			Section 2 -	- No Award No Award No Award	
			Trane U.S. In	ic. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	on 2: Downtown Fort Worth Curry Criminal Justice Cente	•	,		
32	York, YKFDFTQ7-CMGS, Serial: SEXM927730 - Run Inspection	3	NB	NB	
33	York, YKFDFTQ7-CMGS, Serial: SGXM927880 - Stop Inspection	1	NB	NB	
34	York, YKFDFTQ7-CMGS, Serial: SGXM927880 - Run Inspection	3	NB	NB	
Repa	ir Service				
35	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	410	\$ 156.00	\$ 63,960.00	
36	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	1	\$ 234.00	\$ 234.00	
37	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	\$ 311.00	\$ 311.00	

		Section 2 -	- No Award - No Award - No Award		
			Trane U.S. In	nc. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	on 2: Downtown Fort Worth ir Service	(We	st) - HVAC Chill	er Inspection &	Repair Services
	Subtotal Section 2		\$	81,125.00	
	Parts Mark-Up Section 2		80)%	
Sectio	on 3: Suburban Tarrant Cou	nty -	HVAC Chiller In	nspection & Rep	air Services
Dionn	ne Phillips Bagsby Southwes	st Su	bcourthouse		
1	Daikin, AWV012, Serial: STNU170800003 - Stop Inspection	1	NB	NB	
2	Daikin, AWV012, Serial: STNU170800003 - Run Inspection	3	NB	NB	
3	Daikin, AWV012, Serial: STNU170800011 - Stop Inspection	1	NB	NB	
4	Daikin, AWV012, Serial: STNU170800011 - Run Inspection	NB	NB		
Medic	cal Examiner's Office				
5	McQuay, WMC400DBS- ER10, Serial: STNU110300119 - Stop Inspection	1	NB	NB	

			Section 1 - No Award Section 2 - No Award Section 3 - No Award		
				nc. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	cal Examiner's Office				
6	McQuay, WMC400DBS- ER10, Serial: STNU110300119 - Run Inspection	3	NB	NB	
7	McQuay, WMC400DBS- ER10, Serial: STNU110300120 - Stop Inspection	1	NB	NB	
8	McQuay, WMC400DBS- ER10, Serial: STNU110300120 - Run Inspection	3	NB	NB	
9	York, YLAA0091HE46XCBB, Serial: 2BBM023332 - Stop Inspection	1	NB	NB	
10	York, YLAA0091HE46XCBB, Serial: 2BBM023332 - Run Inspection	3	NB	NB	
North	neast Annex				
11	McQuay, AGS120C, Serial: STNU050900048 -	1	NB	NB	

			Section 2 -	- No Award - No Award - No Award	
			Trane U.S. In	ic. dba Trane*	
			Fort We	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
North	neast Annex McOuay_AGS120C				
12	McQuay, AGS120C, Serial: STNU050900048 -	3	NB	NB	
North	Run Inspection			l	
13	York, YLAA0120SE, Serial: 2BBM023507 - Stop Inspection	1	NB	NB	
	York, YLAA0120SE,				
14	Serial: 2BBM023507 - Run Inspection	3	NB	NB	
14 15	Serial: 2BBM023507 - Run	3	NB NB	NB NB	
	Serial: 2BBM023507 - Run Inspection York, YLAA0120SE, Serial: 2BBM023508 -	1			
15 16	Serial: 2BBM023507 - Run Inspection York, YLAA0120SE, Serial: 2BBM023508 - Stop Inspection York, YLAA0120SE, Serial: 2BBM023508 - Run	1	NB	NB	

			Section 2 -	- No Award No Award No Award	
			Trane U.S. In	ic. dba Trane*	
			Fort Worth, TX		
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	on 3: Suburban Tarrant Cou west Subcourthouse	nty -	HVAC Chiller Ir	Ispection & Rep	air Services
18	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900025 - Run Inspection	3	NB	NB	
19	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900038 - Stop Inspection	1	NB	NB	
20	McQuay, AGZ140CHHNN- ER10, Serial: STNU100900038 - Run Inspection	3	NB	NB	
Reso	urce Connection				
21	Carrier, 30GTR050- 521KJ, Serial: 0403F13490 - Stop Inspection	1	NB	NB	
22	Carrier, 30GTR050- 521KJ, Serial: 0403F13490 - Run Inspection	3	NB	NB	

			Section 2 -	- No Award · No Award · No Award	
			Trane U.S. In	ic. dba Trane*	
			Fort Worth, TX		
			HUB:	No	
		-	Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	on 3: Suburban Tarrant Cou ourthouse at Mansfield	nty -	HVAC Chiller Ir	nspection & Rep	pair Services
23	McQuay, AGZ055AS27- ER10, Serial: STNU990400121 - Stop Inspection	1	NB	NB	
24	McQuay, AGZ055AS27- ER10, Serial: STNU990400121 - Run Inspection	3	NB	NB	
25	McQuay, AGZ055AS27- ER10, Serial: STNU021100029 - Stop Inspection	1	NB	NB	
26	McQuay, AGZ055AS27- ER10, Serial: STNU021100029 - Run Inspection	3	NB	NB	
Subco	ourthouse in Arlington				
27	McQuay, AGZ060BH727- ER11, Serial: STNU070600189 - Stop Inspection	1	NB	NB	

			Section 2 -	- No Award No Award No Award	
			Trane U.S. In	ic. dba Trane*	
			Fort W	orth, TX	
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	on 3: Suburban Tarrant Cou ourthouse in Arlington				
28	McQuay, AGZ060BH727- ER11, Serial: STNU070600189 - Run Inspection	3	NB	NB	
29	McQuay, AGZ060BH727- ER11, Serial: STNU070600190 - Stop Inspection	1	NB	NB	
30	McQuay, AGZ060BH727- ER11, Serial: STNU070600190 - Run Inspection	3	NB	NB	
31	McQuay, AGZ060BH727- ER11, Serial: STNU070600192 - Stop Inspection	1	NB	NB	
32	McQuay, AGZ060BH727- ER11, Serial: STNU070600192 - Run Inspection	3	NB	NB	

			Section 2 -	- No Award - No Award - No Award	
				nc. dba Trane*	
			Fort Worth, TX		
			HUB:	No	
			Co-Op:	Yes	
Item	Description	Qty	Unit	Ext	
	on 3: Suburban Tarrant Cou ir Service	inty -	HVAC Chiller Ir	nspection & Rep	air Services
33	Trained Repair Person, Hourly Rate, M – F 8:00 a.m. to 5:00 p.m.	390	NB	NB	
34	Trained Repair Person, Hourly Rate, M – F 5:01 p.m. to 7:59 p.m.	20	NB	NB	
35	Trained Repair Person, Hourly Rate, Weekends and Vendor Recognized Holidays	1	NB	NB	
Subtotal Section 3			NB		
Parts Mark-Up Section 3		NB			
Maximum Response Time - Standard Call - All Sections			24 Hours		
Maximum Response Time - Emergency Call - All Sections			2 H	ours	

^{*}Notes: Response from Trane U.S. Inc. dba Trane did not meet specifications for failing to bid all items within a section as required. Response from The Stone Group did not meet specifications for failing to have an individual with a State of Texas Contractor Class A License on staff as required. Evco Partners submitted a no bid response.